## HISTORIC AMERICAN ENGINEERING RECORD

## INDEX TO PHOTOGRAPHS

Warren King Charcoal Kilns (Birch Creek Charcoal Kilns) Forest Road 188, Targhee National Forest Leadore Vicinity Lemhi County Idaho HAER No. ID-11

James A. McDonald, Photographer September 1988 (ID-11-2 through 9, 11) May 1988 (ID-11-10)

ID-11-1	Photocopy of photograph, showing a view approximately north-northwest of the sixteen original kilns. Photographer and date unknown, but believed to be ca. 1895. Courtesy of Felicia Nichols, Pocatello, Id.
ID-11-2	Contemporary photograph of the view depicted in photograph 1. Isolated kiln at left is the leftmost in photo 1.
ID-11-3	Rear elevations of kilns, looking south. Note loading door and position of kilns on the slope. This placement facilitated access to the upper door.
ID-11-4	Front of isolated (southernmost) kiln. Visible through the doorway are temporary supports installed in 1986.
ID-11-5	Front of northern kiln group, looking northwest. Note cables encircling the walls. Barricades at doorway were placed by Forest Service to prevent cattle from entering the kilns.
ID-11-6	Front of northern kiln group, looking west. Vents, plugged with loose bricks and clay, are distinguishable in the nearest and farthest kilns, slightly above current grade.
ID-11-7	Front of northern kiln group, looking north. Vents are visible in all kilns, in two rows above present grade.
ID-11-8	Detail of typical upper loading door.
ID-11-9	Rear of northern kiln group, looking northeast. Although not visible from this distance, the Viola Mine was located

in the mountain range in the background.

WARREN KING CHARCOAL KILNS (Birch Creek Charcoal Kilns) HAER No. ID-11 (page 2) Index to Photographs

ID-11-10 Detail of plate buckle used to tension wire ropes.
ID-11-11 Remains of Douglas-fir cordwood abandoned when kilns ceased operation, looking northeast.